

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Earl Black PO Box 58 Belfry MT 59008 Phone: (406) 664-3289

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0502954	Blacks Service Station	332 Broadway Ave	Bearcreek	59007	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
9 / S8 Currently in Use	449	5/1/1993 13 / Ye	Diesel 1,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr><tr><td><input checked="" type="radio"/></td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	<input checked="" type="radio"/>	<input checked="" type="radio"/>			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	<input checked="" type="radio"/>																					
<input checked="" type="radio"/>			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
10 / S9 Currently in Use	450	5/1/1993 13 / Ye	Gasoline 1,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr><tr><td><input checked="" type="radio"/></td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	<input checked="" type="radio"/>	<input checked="" type="radio"/>			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	<input checked="" type="radio"/>																					
<input checked="" type="radio"/>			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Maverik Country Stores Inc PO Box 8008 Afton WY 83110 Phone: ( ) -

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0500218	Bridger Maverik Country Store 7	US Highway 310 N	Bridger	59014	(406) 662-3356

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																								
4 / 04 Currently in Use	530	7/21/1991 14 / No	Gasoline 12,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
5 / 05 Currently in Use	531	7/21/1991 14 / No	Gasoline 12,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Town & Country Supply Association 800 E Main PO Box 367 Laurel MT 59044 Phone: (406) 628-6314

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0504498	Town & Country Supply Bridger	209 Main St	Bridger	59014	(406) 662-3623

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
6 / 06 Currently in Use	1515	5/18/1990 16 / No	Diesel 4,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	1516	5/18/1990 16 / No	Gasoline 4,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently in Use	1517	5/18/1990 16 / No	Gasoline 4,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
9 / 09 Currently In Use	4849	7/1/2003 03 / No	Diesel 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I J K <input checked="" type="radio"/> L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Town of Joliet PO Box 210 Joliet MT 59041 Phone: (406) 962-3567

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0500189	Town of Joliet	116 S Main St	Joliet	59041	(406) 962-3567

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 02 Currently In Use	2127	9/1/1997 08 / No	Gasoline 560	Polyethylene Tank Jacket Double-Walled	Galvanized Steel Cathodically Protected	Safe Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Carbon County Road Dist PO Box 887 Red Lodge MT 59068 Phone: (406) 446-1595

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0501853	Carbon County Dist 2 Shop	201 State St	Joliet	59041	(406) 962-3546

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 03 Currently in Use	518	1/30/1992 14 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
2 / 04 Currently in Use	519	1/30/1992 14 / No	Diesel 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Joliet School Dist 7 PO Box 590 Joliet MT 59041 Phone: (406) 962-3541

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0505353	Joliet School Dist 7	131 N Main St	Joliet	59041	(406) 962-3541

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 02 Currently In Use	4091	7/1/1999 07 / No	Diesel 1,000	Polyethylene Tank Jacket Double-Walled	Bare Steel Cathodically Protected	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Dennis Whitmore 1918 Edgewood Dr Billings MT 59102 Phone: (406) 252-4661

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0505577	Country Corner Joliet	110 E Front Ave	Joliet	59041	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently in Use	3925	2/22/1987 19 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	3926	2/22/1988 18 / No	Diesel 1,500	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	3927	2/22/1988 18 / No	Gasoline 2,500	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	3928	2/1/1999 07 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Thomas A George DBA T & D Pump PO Box 14 Roscoe MT 59071 Phone: (406) 328-6722

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0504228	T & D Pump Red Lodge	US Highway 212 N	Red Lodge	59068	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	3869	12/30/1993 12 / No	Gasoline 10,000	Epoxy Coated Steel None	Fiberglass Reinforced Plastic Double-Walled/Non-Corro	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	3870	12/1/1993 12 / No	Diesel 10,000	Epoxy Coated Steel None	Fiberglass Reinforced Plastic Double-Walled/Non-Corro	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	3871	12/1/1993 12 / No	Gasoline 3,000	Epoxy Coated Steel None	Fiberglass Reinforced Plastic Double-Walled/Non-Corro	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Ray Judd Ford Inc PO Box 1190 Red Lodge MT 59068 Phone: (406) 446-1332

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0505655	Ray Judd Ford Inc	116 N Broadway	Red Lodge	59068	(406) 446-1332

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently in Use	1834	4/19/1983 23 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L </div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	1835	4/19/1983 23 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div> <input type="radio"/> A <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input checked="" type="radio"/> K <input type="radio"/> L </div> </div>	Yes Yes Yes Yes
4 / 01 Currently in Use	1833	4/19/1983 23 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div> <input type="radio"/> A <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input checked="" type="radio"/> K <input type="radio"/> L </div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Rockin J Inc PO Box 216 Red Lodge MT 59068 Phone: (406) 446-3123

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0509748	Rock Creek Convenience Store	1022 S Adams Ave	Red Lodge	59068	(406) 446-3123

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																									
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																									
4 / 04 Currently in Use	3389	7/1/1996 10 / No	Gasoline 8,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B				D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						
B				D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
5 / 05 Currently in Use	3390	7/1/1996 10 / No	Gasoline 4,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B				D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						
B				D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Memorial Hospital Association PO Box 590 Red Lodge MT 59068 Phone: (406) 446-2345

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0509926	Beartooth Hospital & Health Center	600 21st St W	Red Lodge	59068	(406) 446-2345

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 02 Currently In Use	3103	10/8/1998 07 / No	Diesel 1,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Rockin J Inc PO Box 216 Red Lodge MT 59068 Phone: (406) 446-3123

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613935	Rock Creek North	902 N Broadway	Red Lodge	59068	(406) 446-3123

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4056	8/1/1999 06 / No	Gasoline 15,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	4057	8/1/1999 06 / No	Gasoline 9,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	4058	8/1/1999 06 / No	Diesel 4,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently In Use	4059	8/1/1999 06 / No	Diesel 2,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Melton Enterprises Inc 4 Cooney Road Roberts MT 59070 Phone: (406) 445-2203

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0506599	Y Stop C Store Inc	4 Cooney Road	Roberts	59070	(406) 445-2203

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently in Use	3329	6/20/1992 14 / No	Gasoline 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	3330	6/20/1992 14 / No	Gasoline 3,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	3331	6/20/1992 14 / No	Diesel 3,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently in Use	3332	6/20/1992 14 / No	Gasoline 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Carbon

**Owner Name and Address:** Thomas H McNew PO Box 80002 Billings MT 59108 Phone: (406) 962-3886

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0507633	Rockvale Travel Plaza UST	US Highway 212 & US Highway 310	Silesia	59041	(406) 962-3886

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
6 / 06 Currently In Use	4112	7/1/1999 07 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently In Use	4113	7/1/1999 07 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently In Use	4114	7/1/1999 07 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed